

---

# MONTHLY NOTAM SUMMARY



DIRECTLINE: +260211271048  
MOBILE: +260967980776  
AFTN: FLKKYNYX  
EMAIL: [ais.lusaka@zacl.aero](mailto:ais.lusaka@zacl.aero)  
WEBSITE: [www.zacl.co.zm](http://www.zacl.co.zm)

**INTERNATIONAL NOTAM  
OFFICE  
ZAMBIA AIRPORTS  
CORPORATION LIMITED  
P.O. BOX 30175, LUSAKA  
ZAMBIA**

NOTAM LIST  
SERIES A  
**DECEMBER 2024**  
ZACL/KKIA/3.3/2.8A

-----  
**The following NOTAMs series (A) are still valid for December 2024. NOTAMs not included in the list have been cancelled, time expired, or superseded by AIP supplement.**  
-----

## **CHECKLIST OF SERIES (A)**

YEAR =2013 0100

YEAR =2023 0043

YEAR =2024 0410 0445 0461 0497 0498 0500 0505 0507 0519 0520 0521 0524 0525 0526 0527  
0529 0530 0531 0532 00536 0547

## MONTHLY NOTAM SUMMARY

LUSAKA (FLFI)		
<b>A0100/13</b>	22-02-13 Permanently: All General Aviation and light aircraft operating into Lusaka, Livingstone, Mfuwe and Ndola International airports should note that all aircraft must be chocked whilst on ground for either short or long-term parking. Refer to IATA airport handling manual, airside management and safety- AHM630 chapter 6.8 and 14.7.2.3.	<b>CHOCKING OF AIRCRAFT</b>
<b>A0497/24</b>	28-11-24 until 25-02-25, Hand amend Zambian AIP ENR 4.4-3 Waypoint TIGEL 172812S0242200E to read as XORIN 172800S0242200E	<b>HAND AMEND ZAMBIAN AIP</b>
<b>A0498/24</b>	28-11-24 until 25-02-25, Hand amend Zambian AIP RNAV STAR RWY 28 TIGEL 1B To read as RNAV STAR XORIN 1B	<b>HAND AMEND ZAMBIAN AIP</b>
<b>A0520/24</b>	26-12-24 until 08-01-25, TRIGGER NOTAM - AIRAC AIP SUP 007/2024 WEF 26 DEC 2024 . Renaming of 5NLC Waypoints in the Lusaka Flight Information Region (FIFI).	<b>RENAMING OF 5NLC WAYPOINTS IN THE LUSAKA FLIGHT INFORMATION REGION (FLFI)</b>
<b>A0525/24</b>	26-12-24 until 08-01-25, TRIGGER NOTAM- AIRAC AIP SUPP 011/2024 WEF 26 DEC 2024.introduction of new ATS routes within Lusaka FIR Lower Airspace	<b>NEW ATS ROUTES WITHIN LUSAKA FIR LOWER AIRSPACE</b>
<b>A0530/24</b>	15-11-24 until 30-12-24, Unmanned aircraft activity will take place within: 124848.07S 0281429.58E 124832.25S 0281414.82E 124835.60S 0281432.74E 121832.17S 0281434.66E 124831.76S 0281439.27E 124825.32S 0281441.71E 124829.33S 0281451.54E 124835.51S 0281446.84E	<b>UNMANNED AIRCRAFT ACTIVITY</b>

## MONTHLY NOTAM SUMMARY

	124845.31S 0281432.51E 124848.07S 0281429.58E	
<b>A0535/24</b>	20-11-24 until 20-12-24 NDB CP Frequency 218KHZ unserviceable.	<b>NDB CP FREQ 218KHZ UNSERVICEABLE</b>
<b>A0536/24</b>	25-11-24 until 25-12-24 NDB MG Frequency 391KHZ unserviceable	<b>NDB MG FREQ 391KHZ UNSERVICEABLE</b>
<b>KENNETH KAUNDA INTERNATIONAL AIRPORT (FLKK)</b>		

<b>A0410/24</b>	12-09-24 until 12-12-24 Hand Amend AIP GEN 3.6.1 Telegraphic Address: Telephone number to read as 260-211271213 instead of 260-211271312.	<b>HAND AMEND ZAMBIAN AIP</b>
<b>A0461/24</b>	08-10-24 until 03-01-25 rehabilitation works of all taxiways at Kenneth Kaunda international Airport (FLKK). Pilots to exercise caution.	<b>REHAHILITATION WORKS OF ALL TAXIWAYS</b>
<b>A0500/24</b>	29-10-24 until 31-01-25 Controller training in tower, approach and area positions. Pilots to exercise patience	<b>CONTROLLER TRAINING</b>
<b>A0505/24</b>	31-10-24 until 28-01-25 Radar control hours of operation. Refer AIP AD2 FLKK1-7	<b>RADAR CONTROL HOURS OF OPERATION.</b>
<b>A0531/24</b>	15-11-24 until 17-12-24, closure of Taxiways Alpha Two, Alpha Three, Golf Two and Taxiway Alpha between intersections Golf One and Golf Three to carry out remedial works within the following coordinates: 151940.4S 0282635.3E 151941.6S 0282635.2E 151947.2S 0282639.4E 151947.4S 0282641.8E 151943.3S 0282638.9E 151941.7S 0282641.1E 151942.2S 0282646.7E 151941.4S 0282646.7E 151941.0S 0282642.0E 151938.8S 0282644.3E	<b>CLOSURE OF TAXIWAYS</b>

## MONTHLY NOTAM SUMMARY

	151938.7S 0282642.8E 151940.7S 0282639.7E 151940.4S 0282635.3E Pilots to exercise caution.	
<b>A0547/23</b>	25-11-24 until 25-02-24 hand amend AIRAC AIP SUPP007/24 to include on AIP AD2 FLKK 1405 EGRAN 150600S 0281612E FLKK IAC ILS Z RWY 10 renamed XUKAT from 26/12/24.	<b>WAYPOINT EGRAN RENAMED XUKAT</b>
<b>HARRY MWANGA NKUMBULA INTERNATIONAL AIRPORT (FLHN)</b>		
<b>A0043/23</b>	03-02-23 Permanently Approach and Runway Lighting, AIRAC AIP AMDT 03/22. RWY EDGE light spacing RWY28 to read 50 meters instead of 60 meters	<b>APPROACH and RUNWAY LIGHTING</b>
<b>A0519/24</b>	10-11-24 until 10-01-25, Controller training on Approach and Tower positions. Pilots to exercise patience.	<b>CONTROLLER TRAINING</b>
<b>SIMON MWANSA KAPWEPWE INTERNATIONAL AIRPORT (FLSK)</b>		
<b>A0507/24</b>	01-11-24 until 26-12-24, AIRAC SUP 009/24 CORRECTION. To read SUP cancels VOR Y RWY 09 and VOR Y RWY 27 instead of ILS Z RWY 09 AND VOR Z RWY 27	<b>AIRAC SUP 009/24 CORRECTION.</b>
<b>A0521/24</b>	26-12-24 until 08-01-25, TRIGGER NOTAM - AIRAC AIP SUPP 009/2024 WEF 26 DEC 2024. Replacement of instrument flight procedure (IFPs) approach charts for Simon Mwansa Kapwepwe International Airport	<b>REPLACEMENT OF IFPs</b>
<b>A0524/24</b>	13-11-24 until 10-02-25, No aircraft operation shall be conducted at the Aerodrome in low visibility condition of RVR 550M.	<b>ACFT OPERATION</b>
<b>A0526/24</b>	26-12-24 until 08-01-25, TRIGGER NOTAM-AIRAC AIP SUPP 008/2024 WEF 26 DEC 2024. Revision of Aerodrome Data for Simon Mwansa Kapwepwe International Airport	<b>REVISION OF AERODROME DATA</b>

## MONTHLY NOTAM SUMMARY

<b>A0527/24</b>	26-12-24 until 08-01-25, TRIGGER NOTAM-AIRAC AIP SUPP 010/2024 WEF 26 DEC 2024. Publication of Aerodrome, Aircraft Parking/Docking, Ground Movement, Obstacle Type A and Type B Charts for Simon Mwansa Kapwepwe International Airport	<b>PUBLICATION OF NEW CHARTS</b>
<b>A0529/24</b>	13-11-24 until 25-15-24 IAC Y VOR RWY 09 dated 24 FEB 2022 Suspended, IAC VOR Y RWY 27 dated 24 FEB 2022 Suspended.	<b>IAC SUSPENDED</b>
<b>A0532/24</b>	15-11-24 until 15-01-25, All aircrafts to park in Power in- Power out position due to non-availability of push back equipment. Pilots to strictly adhere to and follow ATC and Marsheller instructions for parking guidance.	<b>NON-AVAILABILITY OF PUSHBACK EQUIPMENT</b>
<b>MFUWE INTERNATIONAL AIRPORT (FLMF)</b>		
<b>A0445/24</b>	01-10-24 until 24-12-24 Controller TRG on APP and TWR Positions. Pilots to exercise patience.	<b>CONTROLLER TRAINING</b>
<b>AIP Amendment</b>	<b>001/2023</b>	
<b>AIRAC AIP Supplement</b>	<b>011/2024</b>	
<b>AIP Supplement</b>	<b>014/2024</b>	
<b>AIC Series A</b>	<b>039/2024</b>	
<b>AIC Series B</b>	<b>006/2024</b>	

<b>Checklist of AIP Supplements in force</b>	
YEAR=2014	005
YEAR=2015	006
YEAR=2016	004
YEAR=2017	001
YEAR=2021	003 004 015
YEAR=2024	001 002 003 004 005 006 007 008 009 010 011 012 013 014

---

## MONTHLY NOTAM SUMMARY

Checklist of AIRAC AIP Supplements in force	
YEAR= 2023	002 003 004
YEAR =2024	002 003 004 005 006 007 008 009 010 011

---

Iven B Mwenya | Senior Aeronautical Information Services Officer (SAISO)