

DIRECTLINE: +260211271048

MOBILE: +260967980776

AFTN: FLKKYNYX

EMAIL:ais.lusaka@zacl.aero WEBSITE: www.zacl.co.zm

INTERNATIONAL NOTAM
OFFICE
ZAMBIA AIRPORTS
CORPORATION LIMITED
P.O. BOX 30175, LUSAKA
ZAMBIA

**NOTAM LIST** 

**SERIES A** 

**FEBRUARY 2025** 

ZACL/KKIA/3.4/2.8A

-----

The following NOTAMs series (A) are still valid for February 2025. NOTAMs not included in the list have been cancelled, time expired, or superseded by AIP supplement.

\_\_\_\_\_

#### **CHECKLIST OF SERIES (A)**

YEAR =2013 0100

YEAR =2023 0043

YEAR =2024 0497 0498 0500 0524 0547 0565 0576 0579

YEAR =2025 0005 0006 0009 0022 0027 0031 0032 0033

	LUSAKA (FLFI)	
A0100/13	22-02-13 Permanently: All General Aviation and light aircraft operating into Lusaka, Livingstone, Mfuwe and Ndola International airports should note that all aircraft must be chocked whilst on ground for either short or long-term parking. Refer to IATA airport handling manual, airside management and safety-AHM630 chapter 6.8 and 14.7.2.3.	CHOCKING OF AIRCRAFT
A0497/24	28-11-24 until 25-02-25, Hand amend Zambian AIP ENR 4.4-3 Waypoint TIGEL 172812S0242200E to read as XORIN 172800S0242200E	HAND AMEND ZAMBIAN AIP
A0498/24	28-11-24 until 25-02-25, Hand amend Zambian AIP RNAV STAR RWY 28 TIGEL 1B To read as RNAV STAR XORIN 1B	HAND AMEND ZAMBIAN AIP
A0022/25	22-01-25 until 22-02-25 NDB CP Frequency 218KHZ unserviceable.	NDB CP FREQ 218KHZ UNSERVICEABLE
A0031/25	31-01-25 until 13-02-25 NDB SW Frequency 415KHZ unserviceable.	NDB SW FREQ 415KHZ UNSERVICEABLE
A0033/25	20-03-25 until 02-04-25 TRIGGER NOTAM AIRAC AIP Supplement 001/2025 With Effect From 20 <sup>th</sup> March 2025. Amendment of Waypoint Names with 5LNC for Routes and Instrument Flight Procedures (IFP).	AIP SUPP 001/2025
	KENNETH KAUNDA INTERNATIONAL AIR	PORT (FLKK)
A0547/23	25-11-24 until 25-02-24 hand amend AIRAC AIP SUPP007/24 to include on AIP AD2 FLKK 1405 EGRAN 150600S 0281612E FLKK IAC ILS Z RWY 10 renamed XUKAT from 26/12/24.	RENAMED XUKAT

A0027/25	20 01 20 41111 27 01 20 1 44441 00111 01110410 01	RADAR C OF OPER	CONTROL HOURS RATION.	
A0032/25	31-01-25 until 30-04-25 Controller training in tower, approach and area positions. Pilots to exercise patience	CONTROLLER TRAINING		
	HARRY MWANGA NKUMBULA INTERNATIONAL A	AIRPORT	(FLHN)	
A0043/23	03-02-23 Permanently Approach and Runway Lighting, AIRAC AIP AMDT 03/22. RWY EDGE light spacing RWY28 to read 50 meters instead of 60 meters		APPROACH and RUNWAY LIGHTING	
A0576/24	24-12-24 until 24-02-25 Harry Mwaanga Nkumbula International Airport Recertified		FLHN RE- CERTIFIED	
A0005/25	06-01-25 until 05-02-25 Runway Painting for Both 10 and 28. Pilots to Exercise caution.		RUNWAY PAINTING	
A0006/25	06-01-25 until 05-02-25 Taxiway Painting for Both ALPHA and BRAVO. Pilots to adhere to Air Traffic Control instructions.		TAXIWAY PAINTING	
A0009/25	11-01-25 until 14-04-25, Controller training on Approach and Tower positions. Pilots to exercise patience.		CONTROLLER TRAINING	
SIMON MWANSA KAPWEPWE INTERNATIONAL AIRPORT (FLSK)				

A0524/24	13-11-24 until 10-02-25, No aircraft operation shall be conducted at the Aerodrome in low visibility condition of RVR 550M.	ACFT OPERATION		
A0565/24	26-12-24 until 26-03-25 New IAC VOR Z RWY 27 dated 31st October 2024 Suspended.	IAC SUSPENDED		
MFUWE INTERNATIONAL AIRPORT (FLMF)				
A0579/24	30-12-24 until 30-03-25 Controller TRG on APP and TWR Positions. Pilots to exercise patience.	CONTROLLER TRAINING		
AIP Amendment AIRAC AIP Supplem AIP Supplement	001/2023 nent 001/2025 015/2024			

Checklist of AIP Supplements in force				
YEAR=2014	005			
YEAR=2015	006			
YEAR=2016	004			
YEAR=2017	001			
YEAR 2018	004			
YEAR=2021	003 004 015			
YEAR=2024	001 002 003 004 005 006 007 008 009 010 011 012 013 014 015			
Checklist of AIRAC AIP Supplements in force				
YEAR= 2023	002 003 004			
YEAR =2024	002 003 004 005 006 007 008 009 010 011			
YEAR =2025	001			

NOTE : NEXT AIRAC EFFECTIVE DATE 20<sup>TH</sup> FEBRUARY NIL NOTIFICATION

Dismas Shingalili | Senior Aeronautical Information Services Officer (SAISO)